

Fig 1-
Exploded veiw of stabilization tray and button assembly
(post, arm, and button)




Fig 2 -
Back (perspective veiw without endcap)



**Fig 3-
Front (perspective veiwl with endcap)**